## POPPLETON HISTORIC STUDY

B-2759 MAGI HO427595404

Block

Lot

Address

253

27-29

119-123 S. Poppleton Street

Approximate age 1800-1845

1845-1860

1865-1880

1880-1896

1896-on

Rating	Architectural		Condi	tion	
A	Significant-save	good	fair	poor	bad
В	Quality-Indiv./groups-save	good	fair	poor	bad
(c)	Important to street/groups	good	fair	poor	bad
D	Insignificant/detrimental	good	fair	poor	bad

## Notable features:

Ironwork at numbers 117 and 121-123 (after 1850).

Some of these are better maintained than others; all need environmental assistance to survive. A park will be opposite which will help but they need more than that. The houses on Pratt and behind need improvement. This terrace should be rehabilitated.

## Environmental context:

See comments for 125-141 S. Poppleton. These houses also look straight into Lemmon Street to the west, which view should be improved by the proposed park. The lone street tree should be matched with others of equal size.



B-2759 119-123 S. Poppleton Street Block 253 Lot 027-029 Baltimore City Baltimore West Quad.

